



Tech Bulletin

New & Remanufactured Carburetors

#2010-004



*Mallory Marine®
Remanufactured
carburetor*



*Fuel Water Separator Kit
Available in either
aluminum or stainless*



Drain-a-bowl® Kit

Dear Mallory Marine Customer,

We at Mallory Marine occasionally receive carburetors returned for warranty consideration. In most instances, we find the failures are caused by contaminated fuel.

Proper carburetor installation procedures mandate flushing the fuel system and replacing all fuel filters before installing a new or remanufactured carburetor.

Before installing your Mallory Marine® carburetor, please take the time to properly diagnose the original problem or failure.

Any amount of dirt, rust, or debris entering the carburetor will cause it to flood and/or malfunction.

This type of failure is due to improper installation procedure and is not a manufacturing defect, or warranty situation.

If not already equipped with a fuel water separator, we also recommended the installation of a Mallory Marine® Fuel Water separator kit at this time.



Debris removed from a newly installed carburetor, where proper installation procedures were not followed.

Visit our web site www.mallorymarine.com for additional assistance.

