



Tech Bulletin

Mechanical & Electric Fuel Pumps

#2010-006



Mallory Marine®
Electric Fuel Pump



Mallory Marine®
Manual Fuel Pump



Fuel Water Separator Kit
Available in either
aluminum or stainless



Drain-a-bowl® Kit

Dear Mallory Marine Customer,

We at Mallory Marine occasionally receive fuel pumps returned for warranty consideration. In most instances, we find the failures are caused by contaminated fuel.

Proper installation procedures for both manual and electric fuel pumps mandate flushing the fuel system and replacing all fuel filters before installing.

Before installing your Mallory Marine® fuel pump, please take the time to properly diagnose the original problem or failure.

Any amount of dirt, rust, or debris entering the fuel pump may cause it to malfunction. Also, water contaminated fuel, as well as “running dry” are the top causes of electric fuel pump failures. In electric fuel pumps, the fuel actually acts as a coolant.

These types of failures are to improper installation procedures and are not a manufacturing defect, or warranty situation.

If not already equipped with a fuel water separator, we also recommended the installation of a Mallory Marine® Fuel Water separator kit at this time.



Debris removed from a newly installed electric fuel pump, where proper installation procedures were not followed.

Visit our web site www.mallorymarine.com for additional assistance.